

GREG BELL Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER

Division of Oil, Gas and Mining

JOHN R. BAZA

Division Director

| Representatives Present During the Inspection: | | | | | |
|--|-----------------|--|--|--|--|
| Company | Peter Behling | | | | |
| OGM | Karl Houskeeper | | | | |
| l | | | | | |

Inspection Report

| Permit Number: | C0150007 | | | |
|------------------|-----------------------------|--|--|--|
| Inspection Type: | PARTIAL | | | |
| Inspection Date: | Thursday, February 10, 2011 | | | |
| Start Date/Time: | 2/10/2011 8:30:00 AM | | | |
| End Date/Time: | 2/10/2011 1:30:00 PM | | | |
| Last Inspection: | Monday, January 25, 2010 | | | |

Inspector: Karl Houskeeper,

Weather: Clear Skies, Temp. 20 Deg. F. InspectionID Report Number: 2645

> Accepted by: jhelfric 3/3/2011

Permitee: CONSOLIDATION COAL CO Operator: CONSOLIDATION COAL CO

Site: HIDDEN VALLEY MINE

Address: PO BOX 566, SESSER IL 62884

County: EMERY

Permit Type: PERMANENT COAL PROGRAM

Permit Status: RECLAIMED

Current Acreages

| Total Permitted | 960.00 |
|-----------------|--------|
| Total Disturbed | 6.70 |
| Phase I | 6.70 |
| Phase II | |
| Phase III | |

Mineral Ownership

Types of Operations

✓ Underground Federal State Surface Loadout County Fee Processing Other Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Inspector's Signature:

Date

Thursday, Febr



Karl Houskeeper,

Inspector ID Number: 49

Permit Number: C0150007 Inspection Type: PARTIAL

Inspection Date: Thursday, February 10, 2011

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

| | | Evaluated | Not Applicable | Comment | Enforcement |
|------|---|-----------|----------------|----------|-------------|
| 1. | Permits, Change, Transfer, Renewal, Sale | | | | |
| 2. | Signs and Markers | ✓ | | ✓ | |
| 3. | Topsoil | ~ | Y | | |
| 4.a | Hydrologic Balance: Diversions | ✓ | | | |
| 4.b | Hydrologic Balance: Sediment Ponds and Impoundments | ✓ | ✓ | | |
| 4.c | Hydrologic Balance: Other Sediment Control Measures | ✓ | | ~ | |
| 4.d | Hydrologic Balance: Water Monitoring | | | | |
| 4.e | Hydrologic Balance: Effluent Limitations | ✓ | ✓ | | |
| 5. | Explosives | ✓ | ✓ | | |
| 6. | Disposal of Excess Spoil, Fills, Benches | ✓ | ✓ | | |
| 7. | Coal Mine Waste, Refuse Piles, Impoundments | y | ✓ | | |
| 8. | Noncoal Waste | ✓ | | | |
| 9. | Protection of Fish, Wildlife and Related Environmental Issues | | | | |
| 10. | Slides and Other Damage | | | | |
| 11. | Contemporaneous Reclamation | | | | |
| 12. | Backfilling And Grading | | | | |
| 13. | Revegetation | | | | |
| 14. | Subsidence Control | | | | |
| 15. | Cessation of Operations | | | | |
| 16.a | Roads: Construction, Maintenance, Surfacing | | | | |
| 16.t | Roads: Drainage Controls | | | | |
| 17. | Other Transportation Facilities | | | | |
| 18. | Support Facilities, Utility Installations | | | | |
| 19. | AVS Check | | | | |
| 20. | Air Quality Permit | | | | |
| 21. | Bonding and Insurance | | | | |
| 22. | Other | | | | |

Inspection Continuation Sheet

Permit Number: C0150007 Inspection Type: PARTIAL

Inspection Date: Thursday, February 10, 2011

Page 3 of 3

2. Signs and Markers

The mine identification sign was observed in place at the point of contact to the permit area from the public road. The sign contains the required information.

4.c Hydrologic Balance: Other Sediment Control Measures

Checked the silt fence adjacent to the mine identification sign. The silt fence was found to still be functional.